

Work Order Bid (ID)

WORK TO BE PERFORMED IN ACCORDANCE WITH 2011 TENNESSEE WEATHERIZATION FIELD GUIDE and ANY LOCAL CODES. QUESTIONS SHOULD BE DIRECTED TO EAST TENNESSEE RESOURCE AGENCY - WEATHERIZATION DEPT.

WORK ORDER INFORMATION

Work Order Name: WO/60006EA6668/1
Work Order Type: Weatherization
Audit Name: 60006EA6668

CLIENT INFORMATION

Client ID: 60006EA6668

AGENCY INFORMATION

Agency:East Tennessee Human Resource AgencyAgency Phone:(865) 691-2551Address:9111 Cross Park Drive, Suite D100Fax:(865) 531-7216

Knoxville, TN 37923 *Email Address:*

Agency Contact: Alexander, Randy Work Phone:

Cell Phone: (865) 705-8545

Email Address: Ralexander@ethra.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Site Built 1981 1232 Sq. Ft. Concrete Block Walls Metal Roof 200 Amp Square "D" Elecric Box

Client ID: 60006EA6668

Client has severe COPD - Wood Stove affects his breathing. Is bed- ridden.

Measures

	<i>Measure</i> 1	Pre Hung Metal Door @ D	R1		Componen	ts			Inspected
C	comment All	new hardware to be included	d in bid						
					Estimated			Actual	
#	Material / Lab	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure :	2 Infi	Itration Redctn			Componen	its			Inspected
Comment		FM: 3685 ET: 2700							
	1. Wea	atherstrip DR2							
	•	ıst for correct alignment, a rstrip DR3	ıdd 17 Ln.	Ft. int	erior door tr	im, caulk	and		
,	3. Cau	lk Interior all 10 windows							
4	4. Cau	lk @ Ceiling/Wall in bath	(40 Ln. F	t.)					
!	5. Wal	l repair at Front Wall in L/I	R (4 Sq. I	Ft. she	etrock and f	inish)			
(6. Ceil	ing Repair @ L/R (4' x 4'	sheetrock	k and f	inish)				
-	7. Foa	m plumbing penetrations (@ Kit. & B	ath sir	iks (6 pipe:	,		Actual	
# Material / L	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
) Miscellane	eous Su	Infiltration Reduction	Each	1					
Other Detail									
				Measur	e Sub Total:			Sub Total:	
Field Notes	s:						•		

<i>Measure</i> 3 Lig	hting Retrofits			Componen	ts LT1		1	nspected
Comment Contraction CFL's.	ctor to discuss with client	the most e	fficient	areas for in	stallation	n of		
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Lighting	Compact Fl 18 Watt	Each Lamp	6					
2 Labor	Compact Fl 18 Watt	Each Lamp	6					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
	/H Pipe Insulation	Vater Line		Componen	ts			Inspected
	/H Pipe Insulation it. @ Each Hot and Cold V	Vater Line		Componen Estimated			I Actual	Inspected
	•	Vater Line <i>Units</i>	Qty	•		Qty		Inspected
Comment 6 Ln. F	t. @ Each Hot and Cold V			Estimated		Qty	Actual	
Comment 6 Ln. F # Material / Labor	t. @ Each Hot and Cold V	Units	Qty	Estimated		Qty	Actual	
Comment 6 Ln. F# Material / Labor1 Insulation	t. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Oty	Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	t. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Oty	Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	t. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	t. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated			Actual	
Comment 6 Ln. F# Material / Labor1 Insulation2 Labor	t. @ Each Hot and Cold V Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

	leasure 5 DWH mment	Tank Insulation			Componen				Inspected
					Estimated	<u>'</u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
Ot	her Detail						1		
] []		
				Measur	e Sub Total:			Sub Total:	
	Star Emment Contract	gerator Rplcmnt 18 C or to make adjustments dispose of old unit.		-	new unit to f		actor to		Inspected
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0	Refrigerators	Energy Star - Any	Each	1					
1	Labor	Installation Labor	Each	1					
Ot	her Detail								
				Measur	e Sub Total:			Sub Total:	
F	Field Notes:								

Comme		III/Replace Heatpump			Componen	ts HS1,A	AC1		Inspected
		ton window heat pump a on site. Bid to include re			lient is bedri	idden.	s at		
					Estimated			Actual	
# Materi	ial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Heatir	ng Equipmen	Heatpump - 5 kBtu/h Existing, Consult Manual J Data	Each	1					
2 Labor		Heatpump - 5 kBtu/h Existing, Consult Manual J Data	Each	1					
Other De	etail								
				Measur	e Sub Total:			Sub Total:	
		Monitor is Needed voodstove being present			Componen				Inspected
Comme	ent Due to w	oodstove being present			Estimated			Actual	
Comme # Materi	ent Due to w ial / Labor	voodstove being present Description / Comment	Units	Qty	•		Qty		Inspected
Comme # Materi	ent Due to w ial / Labor	oodstove being present		Qty 1	Estimated		Qty	Actual	
Comme # Materi	ent Due to w ial / Labor ecified	voodstove being present Description / Comment	Units		Estimated		Qty	Actual	
Comme # Materi 0 Unspe	ent Due to w ial / Labor ecified	voodstove being present Description / Comment	Units		Estimated		Qty	Actual	
Comme # Materi 0 Unspe	ent Due to w ial / Labor ecified	voodstove being present Description / Comment	Units		Estimated		Qty	Actual	
Comme # Materi 0 Unspe	ent Due to w ial / Labor ecified	voodstove being present Description / Comment	Units Each	1	Estimated			Actual	
Comme # Materi 0 Unspe	ent Due to w ial / Labor ecified etail	voodstove being present Description / Comment	Units Each	1	Estimated Unit Cost			Actual Unit Cost	